



Deltaa Metallix Solutions Private Limited

(AN ISO/IEC17025 NABL Accredited Testing Laboratory)

CIN No.: U71200PN2023PTC224814

New S. No. 72/1/A, Old S. No. 335/1, Plot No. 8, Pragati Colony, Khokale Mala, Attached to Diamond Hotel, 100 Ft. road, Sangli - 416 416

☎ : (+91) 92703 01003

🌐 : www.deltalabsangli.in

✉ : deltalabsangli@gmail.com



Report No.: DMLS/2025-26/9239/37657

ULR No.: TC1384426000009937

Test Report			Format No.: DMLS/F/33
Customer : Vishal Engineering Budhgaon. 1418/16, Dattatray Niwas, near Samarth Mangal Karyalaya, Budhgaon, 416304. Tal-Miraj, Dist-Sangli.	MRN :	DMLS/2025-26/H/5762	
	Sample No/Test Id	S-9239/37657	
	Report Date :	29-03-2026	
	Customer ref./date :	-- 28-03-2026	
	Date of Sample Received :	28-03-2026	

Sample Description provided by customer: Heat No:--, Sample Description: Test specimen.

Material Standard Specification: Copper Base Sample

Test Details

Chemical Test

Discipline: Chemical **Group :** Metals & Alloys

Test Method : Chemical Test BS EN 15079:2015

Tested Date : 29-03-2026

Environment Condition: 22.00 °C

Sample Location : --

Element	Specification	Result
Aluminum (Al) %	--	0.001
Manganese (Mn)%	--	0.001
Iron (Fe)%	--	0.014
Nickel (Ni)%	--	0.55
Zinc (Zn)%	--	0.15
Lead (Pb)%	--	0.051
Phosphorus(P)%	--	0.028
Sulphur(S) %	--	0.011

Remark: .

-- End Of Report --

Disclaimer: "Statements of conformity (e.g. Pass/ Fail)" to specifications are made in this report without taking measurement uncertainty into account except when requested by the customer.

For Deltaa Metallix Solutions Private Limited

4607

Mr. Pavan Yalgude
Tested By

Mr. Pranav Chopade (Dy. Technical
Manager)

Authorized Signatory

Page No: 1/1

■ This Report relates only to the sample(s) submitted & tested. ■ Samples are not drawn by DELTAA METALLIX SOLUTIONS PRIVATE LIMITED.
■ Results pertain to the samples tested only. ■ Test certificate shall not be re-produced except in full without the written approval of laboratory.

P.T.O. for Terms & Conditions ...

Deltaa Metallix Solutions Private Limited

CIN No.: U71200PN2023PTC224814

New S. No. 72/1/A, Old S. No. 335/1, Plot No. 8, Pragati Colony, Khokale Mala, Attached to Diamond Hotel, 100 Ft. road, Sangli - 416 416

☎ : (+91) 92703 01003 🌐 : www.deltalabsangli.in ✉ : deltametallixsolutions@gmail.com



Report No.: DMLS/2025-26/9239/37657-1

Test Report			Format No.: DMLS/F/33
Customer : Vishal Engineering Budhgaon. 1418/16, Dattatray Niwas, near Samarth Mangal Karyalaya, Budhgaon, 416304. Tal-Miraj, Dist-Sangli.	MRN :	DMLS/2025-26/H/5762	
	Sample No/Test Id	S-9239/37657	
	Report Date :	29-03-2026	
	Customer ref./date :	-- 28-03-2026	
	Date of Sample Received :	28-03-2026	

Sample Description provided by customer: Heat No.--, Sample Description: Test specimen.

Material Standard Specification: Copper Base Sample

Test Details

Chemical Test

Discipline: Chemical **Group :** Metals & Alloys

Test Method : Chemical Test BS EN 15079:2015

Tested Date : 29-03-2026

Environment Condition: 22.00 °C

Sample Location : --

Element	Specification	Result
*Copper(Cu)%	--	77.87
*Tin (Sn)%	--	20.59

Remark: .

-- End Of Report --

Disclaimer: "Statements of conformity (e.g. Pass/ Fail)" to specifications are made in this report without taking measurement uncertainty into account except when requested by the customer.

For Deltaa Metallix Solutions Private Limited

Mr. Pavan Yalgude
Tested By

Mr. Pranav Chopade (Dy. Technical
Manager)

Authorized Signatory

Page No: 1/1

■ This Report relates only to the sample(s) submitted & tested. ■ Samples are not drawn by DELTAA METALLIX SOLUTIONS PRIVATE LIMITED
■ Results pertain to the samples tested only. ■ Test certificate shall not be re-produced except in full without the written approval of laboratory.

P.T.O. for Terms & Conditions ..